

---

**WPQ7 - Replacing Front Left and Right Backrest Covers and Headrest Covers (Workshop Campaign)**

---

Vehicle Type: **911 Dakar (992)**

Model Year: **As of 2023 up to 2024**

Equipment: **Full bucket seat (M-no. Q1K)**

Concerns: **Front left and right backrest cover and headrest cover**

Cause: **Due to an allocation error on the parts list, full bucket seats with Shadegreen decorative seam color were installed on the affected vehicles instead of the ordered individual decorative seam color.**

Action: Replace front left and right backrest cover and headrest cover.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation

Position:



*Removing and installing headrest cover on full bucket seat*

- Front left and right backrest cover and headrest cover (**Replace**)

### Required parts

Required Parts: The parts required depending on the respective campaign scope are covered in the “**Warranty processing**” section.

In the “**Parts**” table view in PCSS, the required parts for each scope are marked with the designation “**Scope**” and the respective number of the scope in the column Supplement.

### Required tools

- **VAS 281 003 - Seat assembly fixture**
- Torque wrench, 20-100 Nm (15-74 ftlb.), e.g., **VAS 5820 - Torque wrench, 20-100 Nm (15-74 ftlb.)**
- Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g. **V.A.G 1783 - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**

### Replacing front left and right backrest cover and headrest cover

Work Procedure: 1 Remove front seats. ⇒ *Workshop Manual '72011941 Remove and install front seat (sports bucket seat)'*

- 2 Replace front backrest cover on both front seats. ⇒ *Workshop Manual '74191941 Remove and install front backrest cover (sports bucket seat)'*
- 3 Replace headrest cover on both front seats. ⇒ *Workshop Manual '74211910 Remove and install headrest covering'*
- 4 Install front seats. ⇒ *Workshop Manual '72011941 Remove and install front seat (sports bucket seat)'*
- 5 Enter the campaign in the Warranty and Maintenance logbook.

**Warranty processing**



**Information**

The labor times specified below were determined specifically for carrying out this campaign and may differ from the labor times published in the PCSS Labor Operation List.

Scope 1: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative stitching color **Speed Yellow**

<b>Labor time:</b>	
Replace front left and right backrest cover and headrest cover	Labor time: <b>506 TU</b>
Includes: Remove and install front seats	
<b>Required parts:</b>	
V04015805A 12H	1 piece
⇒ Set of backrest cover	
– Decorative stitching color Speed Yellow	
PAF009057	2 pieces
⇒ Hexagonal fit bolt	
9A700748300	8 pieces
⇒ Hexagonal fit bolt	
⇒ <b>Damage number WPQ7 066 000 2</b>	

Scope 2: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative stitching color **Guards Red**

<b>Labor time:</b>	
Replace front left and right backrest cover and headrest cover	Labor time: <b>506 TU</b>
Includes: Remove and install front seats	

**Required parts:**

V04015805A N13	⇒ Set of backrest cover – Decorative stitching color Guards Red	1 piece
PAF009057	⇒ Hexagonal fit bolt	2 pieces
9A700748300	⇒ Hexagonal fit bolt	8 pieces

⇒ **Damage number WPQ7 066 000 2**

Scope 3: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative seam color **Chalk**

**Labor time:**

Replace front left and right backrest cover and headrest cover Labor time: **506 TU**  
Includes: Remove and install front seats

**Required parts:**

V04015805A OL8	⇒ Set of backrest cover – Decorative seam color Chalk	1 piece
PAF009057	⇒ Hexagonal fit bolt	2 pieces
9A700748300	⇒ Hexagonal fit bolt	8 pieces

⇒ **Damage number WPQ7 066 000 2**

Scope 4: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative seam color **Pebble Grey**

**Labor time:**

Replace front left and right backrest cover and headrest cover Labor time: **506 TU**  
Includes: Remove and install front seats

**Required parts:**

V04015805A OT6	⇒ Set of backrest cover – Decorative seam color Pebble Grey	1 piece
PAF009057	⇒ Hexagonal fit bolt	2 pieces
9A700748300	⇒ Hexagonal fit bolt	8 pieces

⇒ **Damage number WPQ7 066 000 2**

Scope 5: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative seam color **GT Silver**

**Labor time:**

Replace front left and right backrest cover and headrest cover Labor time: **506 TU**  
 Includes: Remove and install front seats

**Required parts:**

V04015805A U01	⇒ Set of backrest cover – Decorative seam color GT Silver	1 piece
PAF009057	⇒ Hexagonal fit bolt	2 pieces
9A700748300	⇒ Hexagonal fit bolt	8 pieces

⇒ **Damage number WPQ7 066 000 2**

Scope 6: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative stitching color **Racing Yellow**

**Labor time:**

Replace front left and right backrest cover and headrest cover Labor time: **506 TU**  
 Includes: Remove and install front seats

**Required parts:**

V04015805A 1S1	⇒ Set of backrest cover – Decorative stitching color Racing Yellow	1 piece
PAF009057	⇒ Hexagonal fit bolt	2 pieces
9A700748300	⇒ Hexagonal fit bolt	8 pieces

⇒ **Damage number WPQ7 066 000 2**

Scope 7: Replace front left and right backrest cover and headrest cover

- Valid for vehicles with decorative stitching color **Black**

**Labor time:**

Replace front left and right backrest cover and headrest cover

Labor time: **506 TU**

Includes: Remove and install front seats

**Required parts:**

V04015805A 7T2	⇒ Set of backrest cover	1 piece
	– Decorative stitching color Black	
PAF009057	⇒ Hexagonal fit bolt	2 pieces
9A700748300	⇒ Hexagonal fit bolt	8 pieces

⇒ **Damage number WPQ7 066 000 2**

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2024 Porsche Cars North America, Inc.