

## **Service Bulletin**

Bulletin No.: 24-NA-058

Date: April, 2024

## **TECHNICAL**

Subject: Malfunction Indicator Lamp (MIL) Illuminated - DTC P062F, P040B, P041B, P0422, P060C, P062B, P1428, P142A, P20EE, P20FE, P22F9, P244A, and/or P244B Set

| Brand:    | Model:                      | Model Year: |      | VIN: |     | Engine:   | Transmission:   |
|-----------|-----------------------------|-------------|------|------|-----|-----------|-----------------|
|           |                             | from        | to   | from | to  | Eligilie. | Halisillission. |
| Chevrolet | Silverado 2500HD/<br>3500HD | - 2024      | 2024 | L5P  | LED |           |                 |
| GMC       | Sierra 2500HD/<br>3500HD    |             |      |      |     | LSP       |                 |

| Involved Region or Country | North America   |  |  |  |
|----------------------------|---|--|--|--|
| Condition                  | Some customers may comment on the MIL illuminated.  Some customers may also comment that the A/C turns off at idle when it is hot outside.  Some technicians may find one or more of the following DTCs set in the Engine Control Module (ECM):  - P062F, P040B, P041B, P0422, P060C, P062B, P1428, P142A, P20EE, P20FE, P22F9, P244A, and/or P244B |  |  |  |
| Cause                      | This condition may be caused by a software anomaly.   |  |  |  |
| Correction                 | Refer to N242438501.  – If N242438501 has been closed, refer to Service Information.  |  |  |  |

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

| Version  | 2   |
|----------|---|
| Modified | Released March 21, 2024 Revised April 16, 2024 - Removed ECM Programing Information and added to Refer to N242438501 in Correction section. |