

Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



© 2012 Mazda Motor of America, Inc.

Subject: MAZDA SERVICE PROGRAM (MSP27) - READINESS CODE FOR EVAPORATIVE MONITORING SYSTEM	Bulletin No: 01-005/12
	Last Issued: 01/27/2012

BULLETIN NOTE

MSP 27 AND SERVICE BULLETIN 01-054/09 ("MAZDA SERVICE PROGRAM (MSP27) - READINESS CODE FOR EVAPORATIVE MONITORING SYSTEM") ISSUED 12/10/09 AND 12/11/09 ARE NO LONGER VALID AND SUPERCEDED BY RECALL 6611K.

APPLICABLE MODEL(S)/VINS

2009-2010 Mazda6 2.5L vehicles produced from April 8, 2008 through October 30, 2009

- VIN Range (2009 Mazda6): 1YVHP8***95M00057 - M52255
- VIN Range (2010 Mazda6): 1YVHZ8***A5M00014 - M21961

2010 CX-7 2.5L vehicles produced from May 21, 2009 through October 21, 2009

- VIN Range: JM3ER****A0300127 - 312034

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical—including photocopying and recording and the use of any kind of information storage and retrieval system—without permission in writing.