

**SB-10044392-8273**

Reference SSM57257

Models X250 / XF

Title Rain Sensing Wipers Not Operating As Expected.

Category Body

Last modified 28-May-2012 00:00:00

Symptom 102000 Window/Glass

Issue:

Rain sensing wipers do not operate as expected.

Cause:

Rain sensor mounting plate debonding from the screen.

Content Action:

Due to the nature of the bonding system it is not currently possible to release a fixing kit to re-bond the sensor mounting bracket to the screen.

Please replace the screen when this issue is confirmed.

Assured VIN # S45960.