

T-SB-0087-12

June 13, 2012

Accelerator Pedal Sensor Assembly Service Precaution

Service Category Engine/Hybrid System

Section Engine Control

Market USA

Toyota Supports ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2001 – 2013	4Runner, Avalon, Camry, Camry HV, Celica, Corolla, FJ Cruiser, Highlander, Highlander HV, Land Cruiser, Matrix, Prius, Prius C, Prius PHV, Prius V, RAV4, RAV4 EV, Sequoia, Sienna, Solara, Tacoma, Tundra, Venza, Yaris	

Introduction

This bulletin provides a service precaution related to the accelerator pedal sensor assembly during inspection, removal, and installation.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-


Accelerator Pedal Sensor Assembly Service Precaution

Service Precaution

PRECAUTION

This accelerator pedal does not require lubrication. Do NOT apply oil or other lubrication to the accelerator pedal sensor assembly. If applied, the accelerator pedal sensor assembly must be replaced.

Figure 1.



1	Accelerator Pedal Sensor Assembly
---	-----------------------------------