

## Opaque coating on inside of lamp unit lens

|                     |  |
|---------------------|--|
| Themen-Nummer       | LI82.10-P-054616                                     |
| Version             | 1  |
| Konstruktionsgruppe | 82.10 Exterior lights                                |
| Stand               | 09-07-2012   |
| Gültigkeit          | MODEL 140.063 /070 /076 ## as of 192208 up to 232041 |
| Änderungsgrund      | Damage code adjusted                                 |
| Sperrgrund          |  |

**Beanstandung:**

Opaque coating on inside of lamp unit lens.

**Ursache:**

Manufacturing residues.

**Abhilfe:**

1. Remove lens of lamp unit ra82001401820x (RA82-1820)
2. Thoroughly clean lens with water and soap or dishwashing detergent, rinse and dry carefully
3. Install lens of lamp unit ra82001401820x (RA82-1820)

**Symptome**

Overall vehicle / Lighting / Exterior lights / Driving lights / Main headlamps / Nonfunctional

**Arbeitswerte**

| Arb.-Nr. | Arbeitstext | Zeit | Schadens-<br>schlüssel | Hinweis |
|----------|-------------|------|------------------------|---------|
|          |             |      | 82A18 B1               |         |
|          |             |      | 82N18 B1               |         |

**WIS-Referenzen**

| Dokument-Nummer | Titel         | Hinweis | Zuordnung    |
|-----------------|---------------|---------|--------------|
| AF82.10-P-2004A | WIS reference |         | Beanstandung |

**Gültigkeit**

| Fahrzeug | Motor | Getriebe |
|----------|-------|----------|
| 140.063  | *     | *        |
| 140.070  | *     | *        |

|         |   |   |
|---------|---|---|
| 140.076 | * | * |
|---------|---|---|