



NUMBER: 14-003-13

GROUP: Fuel System

DATE: March 02, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

Fuel Spit Back During Refueling Due To Inlet Check Valve (X46 Lifetime Warranty Extension)

OVERVIEW:

This bulletin involves replacing the fuel tank with a revised part.

MODELS:

2008 KK Liberty

2007 - 2008 KA Nitro

NOTE: This bulletin applies to gasoline fueled vehicles only and DOES NOT apply to vehicles equipped with the diesel engine.

SYMPTOM/CONDITION:

Some customers may experience a fuel spit back condition during a refueling event.

DIAGNOSIS:

If the customer describes the symptom/condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	CNRSX461AA	Kit, Fuel Tank

REPAIR PROCEDURE:

1. Replace the fuel tank. Refer to DealerCONNECT>Service>TechCONNECT>Service Info>14 - Fuel System>Fuel Delivery, Gas>TANK, Fuel>Removal/Install for additional information.

POLICY:

Reimbursable within the provisions of the warranty.

NOTE: Vehicles included in this Service Bulletin have a lifetime warranty for this repair. See Warranty Bulletin; U.S. D-13-14, Canada SAB 2013-08, or International ID-13-08 for details associated with the extended warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
14-60-01-95	Tank, Fuel - Replace (2 - Skilled)	1.0 hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------