

[Next Unread Message](#)**View Message**

**Sent on** 07 08 2013 **Expires on** 07 22 2013  
**From** Parts and Service Division  
**Subject** Request for Parts: 2007-2010 Odyssey LX & EX with DTC P0325 and/or Engine Kn

**To:** All Honda Service Managers/Advisors  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2007-2010 Odyssey LX & EX with DTC P0325 and/ or Engine Knock

Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2007-2010 Odyssey LXs and EXs that return with a repeat complaint of the Check Engine Light on and the DTC code of P0325 (Knock Sensor Circuit Malfunction) stored and/ or engine knock or ping after having the knock sensor replaced previously for the same symptom.

To fully understand the cause of this occurrence, AHM would like to collect a specific part from the vehicle prior to you attempting a repair of any kind.

**Qualifiers:**

AHM is interested ONLY if the vehicle meets the following requirements:

1. 2007-2010 Odyssey LX or EX.
2. Knock sensor has been replaced previously for P0325 and/ or engine knock or ping.
3. The vehicle has now returned with a Check Engine Light (CEL) on and the DTC P0325 store and/ or engine knock or ping.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.