
2007-2010 Odyssey LX & EX with DTC P0325 and/ or Engine Knock

Background

American Honda (AHM) is investigating certain 2007-2010 Odyssey LXs and EXs that return with a repeat complaint of the Check Engine Light on and the DTC code of P0325 (Knock Sensor Circuit Malfunction) stored and/ or engine knock or ping after having the knock sensor replaced previously for the same symptom.

To fully understand the cause of this occurrence, AHM would like to collect a specific part from the vehicle prior to you attempting a repair of any kind.

Qualifiers:

AHM is interested ONLY if the vehicle meets the following requirements:

1. 2007-2010 Odyssey LX or EX.
2. Knock sensor has been replaced previously for P0325 and/ or engine knock or ping.
3. The vehicle has now returned with a Check Engine Light (CEL) on and the DTC P0325 store and/ or engine knock or ping.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.



Engineering Request for Investigation
