

SB-10052509-3918



Countries:	CANADA, UNITED STATES	Document ID:	IK1600181
Availability:	FleetISIS	Revision:	0
Major System:	CAB / SLEEPER / HOOD	Created:	4/29/2013
Current Language:	English	Last Modified:	4/29/2013
Other Languages:	NONE	Author:	Jon Pierce
Viewed:	14		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 0	 0

Title: Door latch and Rod Rework

Applies To: Cat CT660 ONLY

DESCRIPTION

Door locks do not operate properly, key is bent, or the lock is difficult to open. The electric actuator is firing, but not opening.

For detailed instructions, [Click Here](#)

Hide Details

Feedback Information

Viewed: 13
Helpful: 0
Not Helpful: 0
No Feedback Found