

<p>WATER LEAK AT CENTER PANEL—REAR SLIDING PANEL WINDOW GLASS—MANUAL AND POWER</p>	<p>TSB 13-5-15</p>
---	---------------------------

FORD:
2010-2013 F-150

ISSUE

Some 2010-2013 F-150 vehicles may exhibit a water leak at the side sealing surfaces of the rear glass sliding center panel. This condition may be present on both manual and power sliding panel rear window glass.

ACTION

Follow the Service Procedure Steps to correct this condition

SERVICE PROCEDURE

A service repair kit is now available to resolve this issue. Obtain the Sliding Glass Seal Modification Repair Kit and weatherstrip adhesive. Follow the instruction sheet contained within the kit to resolve the condition.

Obtain Part Locally	
Part Number	Part Description
03602	3M™ Black Super Weatherstrip Adhesive (or Equivalent)

PART NUMBER	PART NAME
AL3Z-15262A80-A	Seal Kit

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage. Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

OPERATION	DESCRIPTION	TIME
130515A	2010-2013 F-150: Modify Seal Following The Kit Instructions (Do Not Use With Any Other Labor Operations)	0.3 Hr.

DEALER CODING

BASIC PART NO.
15422B30

CONDITION
CODE
42

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.