

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR AUGUST 2013**

44141 2011-2014 Edge - MKX Brake Booster Noise After Booster Replacemnet

Some 2011-2014 Edge and MKX vehicles may exhibit a grunt noise from the brake booster typically during the first portion of brake pedal travel and under high-vacuum conditions after replacement of the brake booster in service. This is caused by air in the hydraulic lines and can be corrected by pressure bleeding the brake system. Refer to WSM, Section 206-00 and applicable service labor times.