

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2013**

32216 2013 Escape, Fusion, Edge, Explorer, Taurus, MKT, MKZ With 6F35 Transmission -
Fluid Leak - Seal - Left Side Halfshaft

Some 2013 Escape, Fusion, Edge, Explorer, Taurus, MKT, MKZ vehicles equipped with a 6F35 automatic transmission may exhibit a fluid leak from the left hand (LH) halfshaft seal. This may be due to seal and/or bushing wear caused by the halfshaft surface finish. The case bushing (AL8Z-7025-A) is now a serviceable part. The parts catalog is in process of being updated. Follow the Workshop Manual section 307-01 when replacing bushing, seal and half shaft. Use available service labor times.