

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR JUNE 2013**

32266 2010 to 2013 F150 and Mustang- Built On Or Before 10/31/2012- Outside Door Handle Needs To Be Pulled More Than One Time To Open Door(s)

Some 2010 to 2013 F150 and Mustang vehicles built on or before 10/31/2012 may exhibit a customer complaint of outside door handle needs to be pulled more than one time to open door(s). Perform the Door Handle to Latch Rod Adjustment procedure in the Workshop Manual (WSM), section 501-14 under the General Procedures to correct this condition. Use available service labor times.