

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR JUNE 2013**

32275 2011-2013 Vehicles - MyTouch Functional Issues Due To Phonebook Content - Contact Volume.

Some MyTouch equipped vehicles may experience multiple functional issues such as slow navigation calculations, displayed time jump or audio popping during initial ignition on cycle. These conditions can be created by the size of the contact list within the customers phone book. The amount of data within the contact list can create a processing problem for the module during a key on cycle. This can be resolved by limiting the number and/or content within the contact list. In addition, the automatic phonebook download feature can be set to off by selecting phone, settings, manage phone book, turn auto phone book off. Additional phone contacts can be added by manually re-downloading phone book in that same menu. Recommend following Workshop Manual section 415-00 for additional diagnostics and ensure a master reset is performed.