

SB-10054055-7195

Countries: CANADA, UNITED STATES **Document ID:** IK1200960
Availability: ISIS **Revision:** 0
Major System: ENGINES **Created:** 9/30/2013
Current Language: English **Last Modified:** 9/30/2013
Other Languages: NONE **Author:** Jon Pierce
Viewed: 56

[Less Info](#)
 Hide Details

Coding Information


Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 0	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: Oil Dipstick Clip Breaking

Applies To: CT660

DESCRIPTION

Oil Dipstick tube P clip, and power steering line P clamp may break due to road vibration.

**TOOLS REQUIRED**


Tools	Qty.
basic hand tools	

PARTS INFORMATION

Part #	Description	Qty.
299407C1	Dipstick Clip	1
3985250C1	P.S. Line Clip	1

REPAIR PROCEDURE

Install a more robust set of clips.



 Hide Details

Feedback Information

Viewed: 55
Helpful: 0
Not Helpful: 0

No Feedback Found