

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR NOVEMBER 2013**

44281

SVT RAPTOR - SHOCK ABSORBER WEEPAGE

Some 2010-2013 F-150 Raptor vehicles may have fluid present on the shock absorber shaft-to-body or wetness at the rear reservoir snap-ring. Shock weepage in this area is normal and component replacement for this condition should not occur. Shock absorber weepage will not cause any detrimental effect to the life of the shock absorbers or suspension. If shock absorber assembly is visibly or physically damaged or other suspension symptoms are present, proceed with WSM 204-00 diagnostics to resolve the concern. Replacement of shock assemblies due to weepage may be subject to warranty chargeback.