

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR NOVEMBER 2013**

44292 2014 Fusion Titanium/MKZ - HD Radio Inoperative - Vehicle Built On 9/23/2013 and Through 11/5/2013

Some 2014 Fusion Titanium/MKZ vehicles built on 9/23/2013 and through 11/5/2013 may exhibit the High Definition (HD) radio inoperative with all other radio functions working normally. This may be due to the audio control module (ACM) having an incorrect software configuration. Download as-built data and reconfigure the ACM. Refer to Workshop Manual, Section 418-01 for details and published service labor times.