TOYOTA

Tech Tip T-TT-0270-13

November 02, 2013

HV Battery Cooling System Low Performance "Warning Message"

USA

Service Category

Engine/Hybrid System

Hybrid/Battery Control System

Prius

APPLICABLE VEHICLES

2013-2014

Prius

CONDITION

Drivers of 2013, 2014 Prius vehicles may notice a warning message appear in the multi information display. The warning pertains to diminished performance of the HV Battery Cooling system, possibly due to air flow restriction.

COOLING PERFORMANCE OF THE HYBRID BATTERY IS LOW CONSULT A DEALER

RECOMMENDATIONS

- Check for obstructions to the air inlet area (to the right of the rear seat)
- Check HV Battery Cooling System Fan for dust and debris accumulation.
- Refer to T-SB-0198-11 for more information regarding cleaning and maintaining the HV Battery Cooling system



LINK REFERENCES

1. T-SB-0198-11: '10-'12 Prius: HV Battery Cooling Fan Maintenance for Severe Usage Vehicles

Expires on

11/02/2014

© 2013, Toyota Motor Sales, USA

Page 1 of 1