

**SB-10054929-9832****FORD:**

2014 Fusion

**LINCOLN:**

2014 MKZ

**ISSUE**

Some 2014 Fusion/MKZ Hybrid and Energi vehicles may exhibit an illuminated wrench lamp or red triangle lamp or both with diagnostic trouble code (DTC) P061A present in the powertrain control module (PCM) and/or Secondary On Board Diagnostic Module C (SOBDMC).

**ACTION**

Reprogram the PCM to the latest calibration using IDS release 88.01 and higher. Calibration files may also be obtained at [www.motorcraft.com](http://www.motorcraft.com).

OPERATION	DESCRIPTION	TIME
140018A	2014 Fusion, MKZ Hybrid And Energi: Reprogram The Appropriate Modules As Required By The Software Update Includes Time To Clear Codes After Repair (Do Not Use With Any Other Labor Operations)	0.5 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage  
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
RECALEM	04

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.