

**SB-10054961-1797**  
**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM**  
**FOR DECEMBER 2013**

44333 2011-2014 All-Wheel Drive Vehicles Equipped With PTU Cooling

Some 2011-2014 Explorer that are Export, and 2013-2014 Police Sedan and Utility, Taurus SHO, and Explorer Sport vehicles equipped with AWD and a liquid cooled Power Take-Off Unit (PTU) may experience sludging or contamination of the PTU lube as a result of increased internal lube temperature caused by excessive lube loss from the PTU, or internal PTU failure. Please refer to Workshop Manual (WSM) section 308-07B for PTU diagnosis. If diagnostics lead to replacement of the PTU due to deteriorated lube (sludged or metal contaminants), please also replace the PTU vent hose using base part number 7034 during this repair.