



Date	Group	No.	Release	Page
2.2014	284	052	01	1(7)

SB-10055180-1538

Software Updates
MP7, MP8, US2014
CHU, CXU

PI0839, Software Updates

(February 2014)

Information

Software updates with enhancements are available for the Engine Control Module (ECM), Aftertreatment Control Module (ACM) and Transmission Electronic Control Unit (TECU), if equipped, for MACK vehicles equipped with MACK MP7, and MP8 engines with US2014 emission level. Software updates address the following.

- Regenerations in cold climates (below -20°C [-4°F])
- Piston cooling jet (PCJ) diagnostic fault logic

Required Tools

Premium Tech Tool version 2.02.86 or higher

Diagnostic Connector 88890304

Communication Interface 88890300

Note: Check Premium Tech Tool version by clicking on Help tab and then click on "About Tech Tool".

Procedure

DANGER

Do not attempt to repair or service this vehicle without having sufficient training, the correct service literature and the proper tools. Failure to follow this could make the vehicle unsafe and lead to serious personal injury or death.

- 1 Verify service program eligibility by checking service program status in eWarranty.
- 2 Secure the vehicle for service by parking it on a flat level surface, applying the parking brake, chocking the rear wheels, and placing the transmission in neutral.
- 3 Connect Premium Tech Tool (PTT) to the vehicle diagnostics connector using the 16 pin OBD cable 88890304 and Communication Interface 88890300. Connect the PC to a functional LAN or modem connection and a 120 Volt AC source.
- 4 Turn the ignition switch "ON".
- 5 Log in to PTT and Identify Vehicle is displayed.

- 6 Once the vehicle has been identified, enter the Work Order Number information, then click Start Work.

Work Order Number

Enter a work order number or select a recently used work order number in the list.

Enter work order number:

Select a recently used work order:

Work Order No	User ID	Date
---------------	---------	------

Enter Notes:

Start Work Cancel

W2079940

- 7 From the Main Menu select Program and **then** Program Electronic Control Unit 1700-08-03-39. Then click Start.

Tech Tool

Tech Tool Links Help

Product Product History Diagnose Test Calibrate Program Impact

Program

Select an operation and click Start

- 1700-08-03-39 Program Electronic Control Unit
- 1700-22-03-03 Parameter, programming
- 1700-22-03-28 Accessory Kit
- 1700-22-03-12 Replace Electronic Control Unit
- 1700-22-03-13 Program with Stored Software
- 1700-08-03-40 Handle Component
- 2841-22-03-04 Create Engine Label
- 3810-22-03-10 Change Language

W2079941

8 Select an electronic control unit from the list.

The screenshot shows the 'Tech Tool' application window. At the top, there is a navigation bar with 'Tech Tool', 'Links', and 'Help'. Below this is a menu bar with 'Product', 'Product History', 'Diagnose', 'Test', 'Calibrate', 'Program', and 'Impact'. The 'Program' tab is selected. The main content area displays the instruction 'Select an Electronic Control Unit' followed by a list of control units under the heading 'Control Unit':

- Information display (MID 140)
- Vehicle ECU (MID 144)
- Radio (MID 206)
- Gear Selector ECU (MID 223)
- Aftertreatment Control Module (ACM)
- Engine Control Module (EMS)
- Transmission ECU (TECU)

W2079943

9 Select Program to update the electronic control unit with the latest software.

Programming options

- Update control unit with latest software
- Reload control unit with existing software

W2085461

10 Certain conditions must be met to continue with programming: battery voltage above 10v, parking brake applied, and ignition key in ON position with engine not running. When all conditions have been met, click Continue to proceed with programming.

1700-08-03-39 Program control unit - Update software		
1	> 10 V	12.7 V
2		
3	= 0 rpm 0 rpm	

Automatically checked conditions

- 1 Battery voltage above 10 V
- 2 Parking brake applied
- 3 Ignition key in ON position. Engine not running

W2080113

11 Select "I accept" to agree to the terms and press continue to proceed.

Note: In the United States and Canada, the programming is NOT chargeable. An invoice will not be generated.

1700-08-03-39 Program control unit - Update software

The following control units will be programmed

Engine Control Module (EMS)

Chargeable programming

The software you are about to program is chargeable. If programming is performed using the software, an invoice will be generated. Programming will be charged once even if multiple retries are needed.

The software has commercial part number

85136079 : Engine Control Module

The number can be used for price lookup in your local system and will be specified on the invoice.

I accept


Select I accept to agree to the terms Press Continue to proceed

W2085462

12 When programming is complete, click Exit to return to Main Menu to program the next control unit.

13 For this campaign, update the Engine Control Module (EMS), Aftertreatment Control Module (ACM), and if vehicle is equipped with mDRIVE transmission, Transmission ECU (TECU).

14 Once TECU programming is complete, select Calibrate from the Main Menu. Select 4320-07-03-01 Transmission and clutch, pulling position and click on Start



W2079944

15 When calibration is complete, clear any diagnostic trouble codes and Finish Work.

Reimbursement

This repair is covered by an authorized Service Program. Reimbursement is obtained via the normal claim handling process.	
Claim Type (used only when uploading from the Dealer Bus. Sys.)	41
Recall Status	
Vehicle inspected, repair not required	1- Inspected OK
Vehicle repaired per instruction	2- Modified per instruction
Labor Code	
Primary Labor Code	2304G-01-96 — 1.2 hrs.
Time to take charge and determine campaign status	101AA-0A-00 — 0.3 hrs.
Causal Part	3092091
Authorization Number	PI0839
Expiration Date	28-FEB-2015

Note: Take Charge Time is not included in the Labor Code for this operation. Take charge may be eligible but can only be used once per repair visit. If vehicle is having other warranty repairs performed, take charge should be charged to the warranty repair, otherwise take charge can be charged to this service program.