

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR FEBRUARY 2014

SB-10055648-3596

44408 2001-2004 F-Super Duty Restraint Control Module PMI Difficulty With VCM II

2001-2004 F-Super Duty vehicles may exhibit difficulty attempting to perform programmable module installation (PMI) of the Restraint Control Module (RCM) using VCM II. DTC B1935 and error code 35 may also set along with the inability to perform PMI. This condition is currently being investigated. In the interim, PMI can be performed using VCM I. Monitor OASIS for updates. This condition will be corrected with a future IDS release in 2Q2014.