

## **SB-10056156-7074**

### **ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR MAY 2014**

44526 2013 and 2014 Expedition and Navigator Quarter Glass Delamination Of The Window  
Motor Actuator Puck Built On Or Before 3/26/2014

Some 2013 and 2014 Expedition and Navigator Built on or before 3/26/2014 may experience the Quarter Glass becoming delaminated from the glass actuator puck. Do not attempt to repair this condition by rebonding/attaching the puck. The only authorized repair is glass replacement.