

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2014

SB-10056201-4644

44553 2013-2014 FWD Vehicles - 3.5/3.7L - Engine Oil Leak At Right hand Head-to-Block-to-front cover T-joint

Some 2013-2014 FWD Vehicles equipped with a 3.5 or 3.7L engine, may exhibit engine oil leaking near the outboard right hand cylinder head-to-block-to-front cover T-joint. The leak may appear to be the cylinder head gasket due to oil tracing along the gasket. Investigate the front cover RTV seal as the potential source of the leak.