

**SB-10056252-4249****LINCOLN:**

2013-2014 MKZ

**ISSUE**

Some 2013-2014 MKZ vehicles equipped with a heated steering wheel may exhibit a condition where the heated steering wheel function is inoperative and the heated steering wheel module (HSWM) fails the on-demand self-test, but passes the network test.

**ACTION**

Reprogram the HSWM to the latest calibration using IDS release 90.01 and higher. Calibration files may also be obtained at [www.motorcraft.com](http://www.motorcraft.com).

OPERATION	DESCRIPTION	TIME
140081A	2013-2014 MKZ: Reprogram The HSWM And Clear DTCs (Do Not Use With Any Other Labor Operations)	0.3 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
14B561	04

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.