



# Technical Service Bulletin

## SB-10056332-3844

SUBJECT:			No: <b>TSB-14-54-010</b>
<b>UPDATED HEADLAMP RELAY CIRCUIT – SERVICE MANUAL REVISION</b>			DATE: <b>July, 2014</b>
			MODEL: <b>See below</b>
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER

### PURPOSE

This TSB corrects references in the headlamp relay circuit.

### AFFECTED VEHICLES

2010 – 2013 Outlander  
 2009 – 2014 Lancer  
 2009 – 2014 Lancer Sportback  
 2008 – 2014 Lancer Evolution

### AFFECTED SERVICE MANUALS

2010 – 2013 Outlander Service Manual, Group 90 – Circuit Diagrams → Headlight  
 <Discharge Type (Vehicles with Standard Meter)>  
 <Discharge Type (Vehicles with Color Meter)>

2009 Lancer Service Manual, Group 90 – Circuit Diagrams → Headlight <Discharge Type>

2010 Lancer Service Manual, Group 90 – Circuit Diagrams → Headlight  
 <Discharge Type (Vehicles with Standard Meter)>  
 <Discharge Type (Vehicles with Color Meter)>

2009 Lancer Sportback Service Manual, Group 90 – Circuit Diagrams → Headlight <Discharge Type>


2010 Lancer Sportback Service Manual, Group 90 – Circuit Diagrams → Headlight  
 <Discharge Type (Vehicles with Standard Meter)>  
 <Discharge Type (Vehicles with Color Meter)>

2011 – 2014 Lancer/Lancer Sportback Service Manual, Group 90 – Circuit Diagrams → Headlight  
 <Discharge Type>

2008 – 2014 Lancer Evolution Service Manual, Group 90 – Circuit Diagrams → Headlight <Discharge Type>



Please make the indicated changes to the service manuals listed above.



Copyright 2014, Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website ([www.mitsubishitechinfo.com](http://www.mitsubishitechinfo.com)) (4183)