



Classification:

RS15-001

Reference:

ITB15-009

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

March 5, 2015

## 2015 QX80; DIAGNOSIS AND REPAIR PROCEDURE FOR B00A0 DTC'S

APPLIED VEHICLE: 2015 QX80 (Z62)

### SERVICE INFORMATION

If DTC **B00A0** (OCCUPANT CLASSIFICATION SYSTEM CONTROL UNIT) is set as current in the Air Bag Diagnosis Sensor Unit:

- Follow the "DTC/CIRCUIT DIAGNOSIS" procedure for DTC B1017-B1022 (OCCUPANT SENS C/U) to repair the vehicle.

Refer to the Electronic Service Manual (ESM) section **SRC – SRS Airbag Control System** for procedure.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.