

**ONLINE AUTOMOTIVE SERVICE INFORMATION
FOR MAY 2015**

SB-10058449-6719

45097 2015 Edge - Water Sloshing Noise In The Left Hand (LH) And/Or Right Hand (RH)
Interior Lower Cowl Trim Panel And/Or A Water Leak Into The LH Or RH Floorboard

Some 2015 Edge vehicles may exhibit a water leak at the driver and/or passenger's floor with water entering the vehicle from the a-pillar sheet metal behind the interior lower cowl trim panel. Inspect the body seam located behind the hood hinge where the fender, hood, and a-pillar meet for missing seam sealer. Engineering is currently investigating this concern.