

SB-10058451-7472

ONLINE AUTOMOTIVE SERVICE INFORMATION FOR MAY 2015

45116 2014-2015 Transit Connect - Cornering Lamps Inoperative

Some 2014-2015 Transit Connect vehicles equipped with cornering lamps may exhibit a concern in which the cornering lamps do not illuminate from the turn signal input to the Body Control Module (BCM). Cycling the ignition key Off then On resumes cornering lamp operation but the concern may occur again. This concern may be related to the Headlamp Control Module (HCM) software and is under investigation. Monitor Oasis for updates.