

---

## Mobile phone in general: The ringtone is too loud

---

Topic number	LI82.70-P-061724
Version	1
Design group	82.70 Cellular telephone, voice control system (VCS)
Date	06-26-2015
Validity	205 with Audio 20 code 522 (Audio 20 radio, navigation capable)
Reason for change	
Reason for block	

---

**Complaint:**

The ringtone of an incoming call is too loud.

When the ringtone volume is reduced, the next call is too loud again.

**Cause:**

Software release of head unit (A26/17).

**Remedy:**

Perform software update of head unit (A26/17) with Regio-DVD 05/15, software 15/04.00 or newer.

**Note:**

The ringtone volume can be adjusted either on the customer's phone or on the head unit during the ringing call.

Please do not replace any parts.

<b>Symptoms</b>
Communication/information / Communication / Mobile phone / Telephone / Poor understanding
Communication/information / Communication / Mobile phone / Telephone / Driver cannot be heard
Communication/information / Communication / Mobile phone / Telephone / Driver can be poorly/hardly heard

<b>Work units</b>				
Op. no.	Operation text	Time	Damage code	Note
			8210R EM	Telephone function, poor communication quality/interference noise

<b>Validity</b>			
Vehicle	Engine	Transmission	
205.002	*	*	
205.003	*	*	
205.004	*	*	

# XENTRY

205.005	*	*
205.007	*	*
205.008	*	*
205.009	*	*
205.012	*	*
205.036	*	*
205.037	*	*
205.040	*	*
205.042	*	*
205.043	*	*
205.044	*	*
205.045	*	*
205.047	*	*
205.048	*	*
205.049	*	*
205.064	*	*
205.066	*	*
205.086	*	*
205.087	*	*
205.140	*	*
205.142	*	*
205.143	*	*
205.145	*	*
205.148	*	*
205.164	*	*
205.204	*	*
205.205	*	*
205.207	*	*
205.208	*	*
205.209	*	*
205.212	*	*
205.236	*	*
205.237	*	*
205.240	*	*
205.242	*	*
205.243	*	*
205.244	*	*
205.245	*	*
205.247	*	*
205.248	*	*
205.264	*	*
205.266	*	*
205.286	*	*

XENTRY

205.287	*	*
AMG GT (190)	*	*