

Service Campaign Bulletin

SB-10058543-9863



Mercedes-Benz

Campaign No. 2015070001, July 2015

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 190, Model Year 2016**
Update ESP Control Module Software

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that the software in the ESP Control Module may not meet current production configuration. To correct this condition an authorized Mercedes-Benz dealer will update the ESP Control Module software at the next dealer visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 668 vehicles are affected.

Order No. P-SC-2015070001

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

i Note:

- Use DAS/Xentry 07-08/15 with all associated patches or higher.
- Follow the steps exactly as described in DAS/Xentry.
- Connect battery charger (battery voltage  >12.5V).
- Ensure all electrical consumers are switched-off.
- In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the "pre-call" check list before contacting UHD
- Refer to Star Diagnosis System (SDS) Best Practices Guide.

1. Update ESP control module software: Quick test view / ESP® Electronic Stability Program / Control unit adaptations / Control unit programming.
2. Follow on-screen instructions.

i Note:

The following allowable labor operation should be used when submitting a warranty claim.

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)
 Star Diagnosis System (SDS), Connect/disconnect (02-4762)
 Update ESP control module software (02-9137).

Damage Code	Operation Number	Labor Time (hrs.)
42 960 32 8	02-5058	0.1
	02-4762	0.1
	02-9137	0.1

i Note

Operation Number labor times are subject to change.