

SB-10058614-6920

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JULY 2015

45227 2011-2016 F-Super Duty - Body Cab And/Or Pick-Up Bed Leans To One Side

Some 2011-2016 F-Super Duty vehicles may exhibit a customer complaint of body cab and/or pick-up bed leans to one side. This optical difference may be normal body architecture of vehicle and may be affected by vehicle loading. If a customer complaint of body cab and/or pick-up bed lean is identified, refer to updated diagnostic and repair detail in Professional Technician Society (PTS) Workshop Manual (WSM), Section 204-00. Failure to use the updated diagnostics may lead to incorrect repairs. Make sure no aftermarket components or equipment are affecting the vehicle's body/suspension prior to evaluation or repair. If aftermarket components are found, the vehicle's body/chassis must be returned to original specifications before attempting any repair.