



**Internal notification for: G_0000158986 12180 - Safety Recall - Driver Door
Switch Short Circuit**
gm_gmssg_q01

02/19/2013 05:42 AM

2 attachments



12180 bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 02/19/2013 Ref. number: Service / Field Action / G_0000158986
Subject: 12180 - Safety Recall - Driver Door Switch Short Circuit

GM CUSTOMER CARE AND AFTERSALES
DCS2915
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 19, 2013

Subject: 12180 - Safety Recall
Driver Door Switch Short Circuit

Models: 2006 Chevrolet TrailBlazer EXT and GMC Envoy XL; 2006-07
Buick Rainier, Chevrolet TrailBlazer, and GMC Envoy Currently
or Previously Registered in Connecticut, Delaware, District of
Columbia, Illinois, Indiana, Iowa, Maine, Maryland,
Massachusetts, Michigan, Minnesota, Missouri, New Hampshire,
New Jersey, New York, Ohio, Pennsylvania, Rhode Island,
Vermont, West Virginia, Wisconsin, New Brunswick,
Newfoundland, Nova Scotia, Ontario, Prince Edward Island,
Quebec, Europe, Japan, Russia

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

General Motors is announcing Safety Recall 12180 today. The total number of U.S. vehicles involved is approximately 267,000. Please see the attached bulletin for details.

Customer Letter Mailing
The customer letter mailing will begin on February 26, 2013.

Global Connect (GWM)
The "Investigate Vehicle History" (IVH) screen will be updated February 19, 2013.

Campaign Initiation Detail Report (CIDR)
The CIDR will be available February 19, 2013.