

Internal notification for: G_0000169310 11273A - Special Coverage - Throttle Position Sensor Replacement

gm_gmssg_q01

06/28/2013 05:49 AM

2 attachments

11273A bulletin.pdf

GM Style Sheet.css

Your email client does not support HTML messages

Date:6/28/2013Ref. number:Service / Field Action / G_0000169310Subject:11273A - Special Coverage - Throttle Position Sensor Replacement

GM CUSTOMER CARE AND AFTERSALES DCS2994 URGENT - DISTRIBUTE IMMEDIATELY

Date: June 28, 2013

- Subject: 11273A Special Coverage Revised Throttle Position Sensor Replacement Additional Population Added
- Models: 2008-09 Chevrolet TrailBlazer; GMC Envoy; HUMMER H2 2008-10 HUMMER H3 2008-11 Cadillac Escalade, Escalade ESV, Escalade EXT; Chevrolet Avalanche, Express, Silverado, Suburban, Tahoe; GMC Savana, Sierra, Yukon, Yukon XL; 2009-10 HUMMER H3T 2009-11 Chevrolet Colorado; GMC Canyon Equipped with V8 Engine

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

Bulletin 11273A is being revised to include certain 2011 model year vehicles. The additional number of U.S. vehicles involved is approximately 490,000. Please discard all copies of bulletin 11273.

Customer Letter Mailing

The customer letter mailing for the additional population will begin on July 11, 2013.

Global Warranty Management (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated on a daily basis beginning June 28 through July 8.

Campaign Initiation Detail Report (CIDR) The CIDR is not available for Special Coverage Adjustments.