



**Internal notification for: G_0000167443 12180A - Safety Recall - Driver Door
Switch Short Circuit - Revised**
gm_gmssg_q01

06/05/2013 02:45 PM

2 attachments



12180A bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 6/05/2013

Ref. number: Service / Field Action / G_0000167443

Subject: 12180A - Safety Recall - Driver Door Switch Short Circuit - Revised

**GM CUSTOMER CARE AND AFTERSALES
DCS2980
URGENT - DISTRIBUTE IMMEDIATELY**

Date: June 5, 2013

Subject: 12180A - Safety Recall
Driver Door Switch Short Circuit
Revised Service Procedure

Models: 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL; 2006-07 Buick
Rainier, Chevrolet TrailBlazer, GMC Envoy in Certain States

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Bulletin 12180A has been revised to include additional part numbers in the table shown in Step 3, and a section titled, Door Module Repair Tips, has been added to the service procedure. Please discard all copies of bulletin 12180.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12180A bulletin.pdf Acrobat PDF (1.406MB)
12180A bulletin

name:

Department: -----

Phone:

Intended General Manager, Parts & Service Director, Parts Manager, Service Advisor, Service
roles: Manager, Used Vehicle Sales Manager, Warranty Administrator