



**Internal notification for: G_0000168436 12180B - Safety Recall - Driver Door
Switch Short Circuit - Population Added**
gm_gmssg_q01

06/18/2013 01:08 PM

2 attachments



12180B bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 6/18/2013

Ref. number: Service / Field Action / G_0000168436

Subject: 12180B - Safety Recall - Driver Door Switch Short Circuit - Population Added

**GM CUSTOMER CARE AND AFTERSALES
DCS2988
URGENT - DISTRIBUTE IMMEDIATELY**

Date: June 18, 2013

Subject: 12180B - Safety Recall
Driver Door Switch Short Circuit
Additional Population

Models: 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL; 2006-07 Buick
Rainier, Chevrolet TrailBlazer, GMC Envoy

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Vehicles originally involved in Special Coverage 11323, but have not had the repair performed, have been transferred to Safety Recall 12180 and now appear in IVH.

The closing of the Special Coverage has begun and will be complete in the near future. In the meantime, if a customer comes in with the Special Coverage letter, please perform the repair using Safety Recall Bulletin 12180B and submit the warranty transaction using the appropriate labor code found in the bulletin.

The customer letter mail date for these additional customers has not yet been determined.

Please discard all copies of bulletin 12180A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12180B bulletin.pdf Acrobat PDF (1.401MB)
12180B bulletin