



**Internal notification for: G\_0000169466 12180D - Safety Recall - Driver door  
Switch Short Circuit - Revised**  
gm\_gmssg\_q01

06/28/2013 12:29 PM

2 attachments



12180D bulletin.pdf



GM Style Sheet.css

Your email client does not support HTML messages

Date: 6/28/2013      Ref. number: Service / Field Action / G\_0000169466  
Subject: 12180D - Safety Recall - Driver door Switch Short Circuit - Revised

**GM CUSTOMER CARE AND AFTERSALES  
DCS2998  
URGENT - DISTRIBUTE IMMEDIATELY**

Date: June 28, 2013  
Subject: 12180D - Safety Recall  
Driver Door Switch Short Circuit  
Revised Service Procedure  
Models: 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL; 2006-07 Buick  
Rainier, Chevrolet TrailBlazer, GMC Envoy  
To: All Buick, Chevrolet, and GMC Dealers  
Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

Note Statements have been added to Step 8 of the service procedure, advising technicians to ensure that the protective coating is thoroughly mixed prior to application and that the ESD protective barrier is to be used during the application. Please discard all copies of bulletin 12180C.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

12180D bulletin.pdf Acrobat PDF (1.321MB)  
12180D bulletin

name: E  
Department: Service Department Phone:  
Intended General Manager, Parts & Service Director, Parts Manager, Service Advisor, Service  
roles: Manager, Used Vehicle Sales Manager, Warranty Administrator