



Internal notification for: G_0000155478 Part Availability for Upcoming Safety Recall 12180 - Driver Door Switch Short Circuit
gm_gmssg_q01

01/03/2013 12:01 PM

1 attachment



GM Style Sheet.css

Date: 01/03/2013

Ref. number: Service / Field Action / G_0000155478

Subject: Part Availability for Upcoming Safety Recall 12180 - Driver Door Switch Short Circuit

GM SERVICE AND PARTS OPERATIONS
DCS2873
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 3, 2013

Subject: Part Availability Update For Upcoming Safety Recall 12180 -
Driver Door Switch Short Circuit

Models: Certain 2006 Chevrolet Trailblazer EXT and GMC Envoy XL;
2006-2007 Chevrolet Trailblazer, GMC Envoy, Buick Rainer
and Saab 9-7x Vehicles Originally Sold or Currently Registered
in Connecticut, Delaware, District of Columbia, Illinois, Indiana,
Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota,
Missouri, New Hampshire, New Jersey, New York, Ohio,
Pennsylvania, Rhode Island, Vermont, West Virginia and
Wisconsin

To: All GM Dealers

Attention: General Manager, Parts and Service Director, Parts Manager,
Service Manager, Service Advisor, Used Vehicle Sales
Manager, and Warranty Administrator

PRODUCT FIELD ACTION UPDATE

On August 16, 2012 and October 9, 2012 dealers were advised via GM Global Connect messages of pending safety recall 12180. This product field action involves certain 2006 Chevrolet Trailblazer EXT and GMC Envoy XL; 2006-2007 Chevrolet Trailblazer, GMC Envoy, Buick Rainer and Saab 9-7x vehicles originally sold or currently registered in Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia and Wisconsin.

In October 2012 owners were contacted by letter and advised of this condition. In that letter owners were advised that parts were not yet available.