



GROUP  
Climate Control

MODEL  
2014MY  
Soul (PS)

NUMBER  
PS300

DATE  
May 2014



## TECHNICAL OPERATIONS

**SUBJECT:** INCORRECTLY ROUTED HIGH PRESSURE A/C LINE

Some 2014 Soul (PS) produced prior to February 7, 2014, may exhibit a concern related to poor performance from the A/C system, accompanied by low refrigerant. In such cases, check the routing for the A/C high pressure line to make sure it is not coming into contact with the accessory drive belt (see image). If the line has come into contact with the belt and has sustained damage, replace the line and recharge the system to resolve the concern.

