



**Internal notification for: G_0000156288 11323 - Special Coverage - Driver
Door Switch Short Circuit
gm_gmssg_q01**

01/16/2013 05:35 AM

2 attachments



11323 bulletin .pdf GM Style Sheet.css

Your email client does not support HTML messages

Date: 01/16/2013 Ref. number: Service / Field Action / G_0000156288
Subject: 11323 - Special Coverage - Driver Door Switch Short Circuit

**GM CUSTOMER CARE AND AFTERSALES
DCS2881
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 16, 2013
Subject: 11323 - Special Coverage Adjustment
Driver Door Switch Short Circuit
Models: 2006 Chevrolet TrailBlazer EXT and GMC Envoy XL; 2006-07
Buick Rainier, Chevrolet TrailBlazer, GMC Envoy
To: All Buick, Chevrolet, and GMC Dealers
Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

General Motors is announcing Special Coverage Adjustment 11323 today. The total number of U.S. vehicles involved is approximately 189,000. Please see the attached bulletin for details.

Customer Letter Mailing
The customer letter mailing will begin on January 28, 2013.

Global Connect (GWM)
The "Investigate Vehicle History" (IVH) screen will be updated January 16, 2013.

Campaign Initiation Detail Report (CIDR)
The CIDR is not available for Special Coverage Adjustments.

**END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES**

Message Attachment(s):