

## Tony Lawrence

---

**From:** Tony Lawrence  
**Sent:** Thursday, July 03, 2014 5:24 PM  
**To:** All Dlrs All Rgns - PT; All Dlrs All Rgns - SR  
**Subject:** MAZDA DEALER NOTICE - SERVICE BULLETIN RELEASE

### **SERVICE BULLETIN RELEASE - 07/03/2014**

2014 INDEX: [http://www.mstore2000.com/PDF\\_Files/index07-03-14.pdf](http://www.mstore2000.com/PDF_Files/index07-03-14.pdf)

The following Service Bulletin has just been issued.

- For latest MS3 postings, click here: <https://portal.mazdausa.com/m173/service/esi/MazdaServiceShop>

- For printable PDF files from MStore, click on the link below each TSB title:

\* If the links do not automatically take you directly to the document, cut and paste the link into your internet browser address window and press enter.

### **NEW BULLETIN**

09-029/14 - 2010-2013 MAZDA6 - SEAT CUSHION TRIM COMING APART AT SEAMS - (CLOTH SEATS ONLY)

[http://www.mstore2000.com/PDF\\_Files/09-029-14-2855.pdf](http://www.mstore2000.com/PDF_Files/09-029-14-2855.pdf)

- Please distribute this information to all parts and service personnel.
- If you no longer wish to receive Mazda service bulletins, please contact the IT Administrator at your dealership and ask them to remove your email address from under the EMDCS application.

© 2014 Mazda Motor of America, Inc.


<b>Subject:</b> SEAT CUSHION TRIM COMING APART AT SEAMS - (CLOTH SEATS ONLY)	<b>Bulletin No:</b> 09-029/14
	<b>Last Issued:</b> 07/03/2014

## APPLICABLE MODEL(S)/VINS

2010-2013 Mazda6 vehicles equipped with cloth seats

## DESCRIPTION

Some vehicles may exhibit a condition where the front and/or rear seat cushion trim is coming apart at the seams.



Seat cushion trim(s) with increased strength are available to eliminate this concern.

Customers having this concern should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE

1. Verify the customer concern.
2. Replace **only the affected** seat cushion trim(s) with a new one according to the instructions on MS3 online or the Workshop Manual (section 09-13 FRONT SEAT CUSHION TRIM REMOVAL/INSTALLATION) and/or (section 09-13 REAR SEAT CUSHION TRIM REMOVAL/INSTALLATION).
3. Verify the repair.

**PART(S) INFORMATION**

Part Number		Description	Qty.	Notes
New	Old			
GEY0-88-161	GEG1-88-161 -02	Front seat cushion trim	1	Driver side STA (Black)
GEY1-88-161	GEG1-88-161 -30	Front seat cushion trim	1	Driver side STA (Beige)
GEY2-88-161	GEG2-88-161 -02	Front seat cushion trim	1	Driver side STB (Black)
GEY3-88-161	GEG2-88-161 -30	Front seat cushion trim	1	Driver side STB (Beige)
GEY0-88-111	GEG1-88-111 -02	Front seat cushion trim	1	Passenger side (Black)
GEY1-88-111	GEG1-88-111 -30	Front seat cushion trim	1	Passenger side (Beige)
GEY0-88-201	GEG1-88-201 -02	Rear seat cushion trim	1	Rear seat (Black)
GEY1-88-201	GEG1-88-201 -30	Rear seat cushion trim	1	Rear seat (Beige)

**WARRANTY INFORMATION**

**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	87
Damage Code	9A
Part Number Main Cause	(SEE PART(S) INFORMATION)
Quantity	1
Operation Number / Labor Hours:	XXJDHXR / 0.9 Hrs. (Front seat / one side) XXJDJXR / 1.5 Hrs. (Front seat / both sides) XXJDKXR / 1.5 Hrs. (Rear seat) XXJDLXR / 2.1 Hrs. (Front seat / one side and rear seat) XXJDMXR / 2.7 Hrs. (Front seat / both sides and rear seat)

**NOTE:**

- This bulletin only applies to vehicles with cloth seats.
- Replace **only the affected** seat cushion trim(s).