

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Friday, April 25, 2014 7:41 AM  
**To:**  
**Subject:** Internal notification for: G\_0000190649 Safety Recalls 13454A, 14063A, 14113A, and 14133A - Revised  
**Attachments:** 13454A Bulletin.pdf; 14063A Bulletin.pdf; 14113A Bulletin.pdf; 14133A Bulletin.pdf

---

Date: 4/25/2014

Ref. number: Service / Field Action / G\_0000190649

Subject: Safety Recalls 13454A, 14063A, 14113A, and 14133A - Revised

---

**GM CUSTOMER CARE AND AFTERSALES  
DCS3196  
URGENT - DISTRIBUTE IMMEDIATELY**

**Date:** April 25, 2014

**Subject:** Safety Recall Bulletins 13454A, 14063A, 14113A and 14133A  
Ignition Switch / Ignition Lock Cylinder / Ignition Key  
Service Procedure and Warranty Transaction Submission  
Sections Revised

**Models:** 2005-2010 Chevrolet Cobalt  
2006-2011 Chevrolet HHR  
2006-2010 Pontiac Solstice  
2005-2006 Pontiac Pursuit (Canada Only)  
2007-2010 Pontiac G5  
2003-2007 Saturn Ion  
2007-2010 Saturn Sky

**To:** All General Motors Dealers

**Attention:** General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

The Service Procedure and Warranty Transaction Submission sections in the subject bulletins have been revised. This was done to clarify certain repair steps and provide a required add time. Please see the attached bulletins for details. Please discard all copies of bulletins 13454, 14063, 14113 and 14133.

**END OF MESSAGE**