

Subject

Audio, clock and cigarette lighter port shut off

Market

USA

Service Category

Power Source/Network

Section

Power Distribution

Applicability

2010-2013MY Corolla
APPLICABLE VEHICLES

2010-2013

Corolla

CONDITION

The radio receiver turns off intermittently along with the clock and cigarette lighter port.

RECOMMENDATIONS

When multiple electrical components become inoperative simultaneously, it may be caused by a common power source/ground problem. Be sure to check the ACC relay, fuses, and any common power wiring or ground points when diagnosing this condition.

LINK REFERENCES

- [AUDIO / VIDEO: AUDIO AND VISUAL SYSTEM: Radio Receiver Power Source Circuit; 2011 MY Corolla \[12/2010 - ???????\]](#)
- [AUDIO / VIDEO: AUDIO AND VISUAL SYSTEM: Radio Receiver Power Source Circuit; 2010 MY Corolla \[01/2009 - ???????\]](#)
- [AUDIO / VIDEO: AUDIO AND VISUAL SYSTEM \(w/ Multi-display\): Radio Receiver Power Source Circuit; 2012 MY Corolla \[12/2011 - ???????\]](#)
- [AUDIO / VIDEO: AUDIO AND VISUAL SYSTEM \(w/o Multi-display\): Radio Receiver Power Source Circuit; 2012 MY Corolla \[12/2011 - ???????\]](#)
- [AUDIO / VIDEO: AUDIO AND VISUAL SYSTEM \(w/ Multi-display without DVD Player\): Radio Receiver Power Source Circuit; 2013 MY Corolla \[07/2012 - ???????\]](#)