

NUMBER: 23-003-13 REV. A

GROUP: Body

DATE: January 29, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 23-003-13, DATED JANUARY 19, 2013, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE LABOR OPERATION NUMBER CHANGES.**

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-005. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Left And/Or Right Rear Interior Speaker Bolster Is Raised At Quarter Panel Trim

OVERVIEW:

This bulletin involves inspecting and if necessary replacing the right and/or left rear interior speaker bolster trim.

MODELS:

2013 (RT) Caravan / Town and Country

NOTE: This bulletin applies to vehicles equipped with (sales code -X1) Graystone interior built after September 17, 2012 (MDH0917XX) and before September 19, 2012 (MDH0919XX)

SYMPTOM/CONDITION:

Left and/or right rear interior speaker bolster is raised at quarter panel trim

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	0ZT83BD1AG	Left, Rear Speaker Bolster
1 (AR)	0ZT82BD1AG	Right, Rear Speaker Bolster

REPAIR PROCEDURE:

1. Inspect the right and left rear speaker bolster at the area shown in (Fig. 1). Was the speaker bolster over flush and seated on the A-surface of the quarter panel trim?
 - a. Yes>>> Remove and replace the right and/or left rear speaker bolster. Refer to the detailed service procedures available in: DealerConnect> TechCONNECT under: Service Info> 23-Body> Interior> Panel, Quarter Trim, Bolster> Removal/Installation.
 - b. No>>> Proceed to [Step #2](#).




Fig. 1 Speaker Bolster Trim

- 1 - Over flush and seated on the a-surface of the interior quarter panel trim
- 2 - Interior speaker bolster
- 3 - Interior quarter panel trim

2. Return the vehicle to the customer or dealer inventory.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
23-20-56-93	Inspect The Right And Left Rear Speaker Bolster Trim Only (1 - Semi-Skilled)	0.2 Hrs.
23-20-56-94	Inspect The Right And Left Rear Speaker Bolster Trim And Replace One Side Only (1 - Semi-Skilled)	0.2 Hrs.
23-20-56-95	Inspect The Right And Left Rear Speaker Bolster Trim And Replace Both Sides (1 - Semi-Skilled)	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------