

**Service Action K213: Brake Pad Wear Warning
Indicator Light**

30-APR-14 | No.: 6-227USA | Section: GENERAL INFORMATION | Market: USA

DESCRIPTION

A select number of 2013 model year Jaguar XF (X250) vehicles, fitted with the 3.0L SC engine and within the listed VIN range only, where the Brake Pad Wear Warning Indicator may be inoperative due to non-activation within the Car Configuration File.

AFFECTED VEHICLES

The VIN range of affected vehicles is S51674-S60957. See attached list.

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin K213: *Service Action: Brake Pad Wear Warning Indicator Light*, for detailed repair instructions.

PARTS

No parts required

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY

△ NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**K213**' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **30 April 2016** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No.	QTY.
K213	B	Update Car Configuration File	86.99.94	0.20	-	-
K213	C	Update Car Configuration File	86.99.94	0.20	-	-
		Drive in/drive out	10.10.10	0.10	-	-

Normal Warranty policies and procedures apply

Service Action K213: Affected VIN List

VIN	DEALER NAME
S51674	Jaguar Plano
S51677	Jaguar Palm Beach
S55273	Jaguar Chantilly
S55274	Imperial Motors Jaguar of Lake Bluff
S55278	Jaguar Palm Beach
S55279	Jaguar Palm Beach
S55992	Jaguar Plano
S55993	Jaguar Chantilly
S56011	British Motor Car Distributors, Ltd.
S56014	Jaguar Palm Beach
S56015	Jaguar Hartford
S56021	Cherry Hill Classic Cars
S56025	Imperial Motors Jaguar of Lake Bluff
S56026	Imperial Motors Jaguar of Lake Bluff
S56031	Cherry Hill Classic Cars
S56032	Jaguar Chantilly
S56038	Jaguar Plano
S56040	British Motor Car Distributors, Ltd.
S56044	Jaguar Chantilly
S56048	British Motor Car Distributors, Ltd.
S56081	Jaguar Plano
S56082	Cherry Hill Classic Cars
S56086	Jaguar Palm Beach
S60082	Imperial Motors Jaguar of Lake Bluff
S60860	Imperial Motors Jaguar of Lake Bluff
S60867	Madison Jaguar
S60877	Madison Jaguar
S60887	Madison Jaguar
S60947	Madison Jaguar
S60957	Imperial Motors Jaguar of Lake Bluff