

Reference	SSM71894
Models	LR2 / L359 Range Rover Evoque / L538
Title	Injector faults on 2.0GTDI engine.
Category	Engine
Last modified	03-Jul-2014 00:00:00
Symptom	404000 Fuel System Concerns

ContentIssue:

Only applicable to L538 (Evoque) and L359 (LR2, Freelander 2) vehicles fitted with 2.0GTDI engines.
Warranty data indicates a volume of **fuel injectors** being replaced in relation to the symptom outlined below:

Vehicles suffering from a misfire at cold start and on some occasions intermittent rough running at normal operating temperature, with various DTC's stored such as P0300-00 P0301-00 P0302-00 P0304-00 P1315-00 P0316-00

Cause:

Engineering would like to gain further understanding into the cause of these fuel injector failures.

Action:

On all occasions whereby a vehicle suffering from the above symptom/s is diagnosed with a faulty fuel injector, please submit an EPQR detailing the diagnostic procedure carried out. Product Investigation will monitor these quality reports with a view to raise a priority return request (PRR) for several selected parts for root cause diagnosis.