



Technical Bulletin

Model(s)	Year	Engine Code	Trans. Code	VIN Range From	VIN Range To
Jetta (A5)	2005-2008	All	All	All	All
Jetta Wagon (A5)	2008	All	All	All	All

Condition

57 13 01 November 11, 2013 2035718

Procedure for Communication Interruptions Following Door Control Module - Window Motor Replacement

Technical Background

The latest generation door control module, which are Unified Diagnostic Service (UDS) diagnosis compatible, are available for repair or part exchange on the models named above. Please note, in individual cases, there may be communication problems with the newly installed door control module during diagnosis and connection (coding, adaption, parametering etc.).

Production Solution

Not applicable.

Service

Please follow the information found in Parts Bulletin 9-130. For additional assistance, please contact the Parts Technical Helpline at 1-800-767-6552.

Warranty

Information only.



Technical Bulletin

Required Parts and Tools

No Special Parts required.

No Special Tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.