File in Section:

Bulletin No.: PI0716A

Date: April, 2013

# PRELIMINARY INFORMATION

Subject: Road Debris (Mud) on Rocker Panel at Front Door Area

Models: 2010-2013 GMC Terrain

This PI is being revised to add the 2013 model year. Please discard PI0716.

## Condition/Concern



2813065

Some customers may comment that road debris (mud) is traveling up between the front doors and the rocker panels. This condition may be caused by debris working around the front of the door seal.

#### Recommendation/Instructions

**Note:** Whenever you drill into a metal surface, the corrosion resistance of that panel is compromised. Treat the drilled holes with GM Super Lube® to prevent corrosion.

The installation of GM accessory splash guards will direct the debris away from the door seal and prevent mud from working into the rocker panel area.

Splash guards are available as P/N 19170501 for front splash guards only, or P/N 19170503 for all four splash guards.

### **Parts Information**

Part Number	Description
19170501	GUARD PKG, F/FDR MUD
19170503	GUARD PKG, FRT MUD & RR MUD
12371287 (in Canada, use 10953437)	GM Vehicle Care Super Lube® with PTFE

# **Warranty Information**

Please advise the customer that the installation and cost of this repair will not be covered under the vehicle's warranty.