



# Service Bulletin

File in Section: -

Bulletin No.: P11009

Date: July, 2013

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tips for DTCs P0097, P00F4, P0113, P2229 and/or P0102 Set

**Models:** 2013-2014 Buick Enclave, LaCrosse  
2013-2014 Cadillac ATS, CTS, SRX, XTS  
2013-2014 Chevrolet Captiva, Equinox, Impala, Traverse  
2014 Chevrolet Impala Limited  
2013-2014 GMC Acadia, Terrain  
Equipped with 3.0L and 3.6L Engine (RPOs LFW, LLT, LFX)

### Condition/Concern

Some customers may comment on the service engine soon (SES) light being on. Upon inspection, a technician may find DTCs P0097, P00F4, P0113, P2229 and/or P0102 set.

This condition may be caused by disconnecting the mass air flow (MAF) sensor with the ignition key on and/or the engine running while servicing the A/C Freon fill port, air filtration system or other components under the hood.

### Recommendation/Instructions

If any of these codes become present during service work, recheck the connection to ensure the proper click engagement for the connector and clear all the codes.